
STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

1594 West North Temple Suite 1210 Box 145801

Salt Lake City, Utah 84114-5801 Telephone: (801) 538-5291 Fax: (801) 359-3940



ANNUAL REPORT OF MINING OPERATIONS

The informational requirements of this form are based on provisions of the Mined Land Reclamation Act, Title 40-8, Utah Code Annotated 1953, as amended, and the General Rules as promulgated under the Utah Minerals Regulatory Program. An operator conducting mining operations under a Notice of Intention must file an annual operations and progress report (FORM MR-AR) with the Division.

I.	General Information							
	1.	Report Time Period: From (mo./yr.) 1/97 To (mo./yr.) 12/97						
	2.	DOGM File Number (Mine No): M /045 /037						
	3.	Mine Name: Morton Salt / Grantsville						
	4.	Mineral(s) Mined (or permitted to mine): Salt (Sodium Chloride)						
	5.	Type of mine Surface Mine or Underground Mine						
	6.	Legal Description (Location of Lands Affected):						
		1/4,1/4,1/4, Section, Township, Range						
		1/4,1/4,1/4, Section, Township, Range						
		1/4,1/4,1/4, Section, Township, Range						
7.	Name	Name of Operator or Company: Morton International, Inc., Morton Salt						
	8.	Permanent Street Address: I-80 West Exit 84						
		City, State, Zip: Grantsville, UT 84029						
		Phone: 801-250-6335						
	9. Company Representative (or designated operator):							
		Name:James H. Huizingh						
		Title:Facility Manager						
		Business Address:I-80 West Exit 84 (P.O. Box 506)						
		City, State, Zip: Grantsville, UT 884029						
		Phone: 801-250-6335						
		Please check if any of the above information has changed since previous year. (Company Rep)						
II.	Mining and Reclamation							
	1.	Was the mine active during the past year? Yes ☒ No ☐						
	2.	If active, how much ore or mineral was mined?716,237						
	3.	If inactive, what year was the mine last active?						

4.	Briefly describe any new or additional surface disturbances that occurred during the past year. This description should include the type of work performed, and volume of material moved. Repair and maintenance of existing dykes.					
5.	How much acreage was reclaimed during the past year?0					
6.	Briefly describe the reclamation work performed during the past year. This description should include methods employed, and an evaluation of the results.					
7.	What is the total disturbed acreage at years end?15,000					
8.	Briefly summarize any mining and/or reclamation plans for the upcoming year. We anticipate harvest of the same pond acreage annually.					
	•					
<u>ΓΕ</u> :	Section III., "Additional Information" applies only to large mining operations.					
TE : Additional .						
<u>Additional</u>	Section III., "Additional Information" applies only to large mining operations.					
<u>Additional</u>	Section III., "Additional Information" applies only to large mining operations. **Information** An updated surface facilities map should be attached if there have been significant changes since the property of the proper					
Additional 1.	Section III., "Additional Information" applies only to large mining operations. Information An updated surface facilities map should be attached if there have been significant changes since the pwas submitted. Any monitoring results or other reports that are required under the terms of the approved notice of interesting the surface of the provided in the surface of the provided in the surface of the provided in the surface of the surf					
1. 2. Signature	Section III., "Additional Information" applies only to large mining operations. Information An updated surface facilities map should be attached if there have been significant changes since the pwas submitted. Any monitoring results or other reports that are required under the terms of the approved notice of intshould also be attached.					
1. 2. Signature	Section III., "Additional Information" applies only to large mining operations. Information An updated surface facilities map should be attached if there have been significant changes since the pwas submitted. Any monitoring results or other reports that are required under the terms of the approved notice of inshould also be attached. Requirement					
1. 2. Signature	Section III., "Additional Information" applies only to large mining operations. Information An updated surface facilities map should be attached if there have been significant changes since the pwas submitted. Any monitoring results or other reports that are required under the terms of the approved notice of inshould also be attached. Requirement by certify that the foregoing is true and correct.					
1. 2. Signature	Section III., "Additional Information" applies only to large mining operations. Information An updated surface facilities map should be attached if there have been significant changes since the pwas submitted. Any monitoring results or other reports that are required under the terms of the approved notice of intended also be attached. Requirement by certify that the foregoing is true and correct. Name (Typed or Print): James H. Huizingh Facility Manager					

jb MR-AR

LOCATION OF OPERATION:

County:	Tooele						
Township:	1N	Range:	5W	Section(s):	19		
Township:	1N	Range:	6W	Section(s):	24, 25, 26, 32, 33, 34, 35		
Township:	1S	Range:	5W	Section(s):	16, 19, 20, 21		
Township:	1S	Range:	7W	Section(s):	1, 2, 3, 10, 11, 12, 13, 14, 15		
Township:	1S	Range:	6W	Section(s):	2, 3, 4, 5, 6, 7, 8, 9, 10, 11,		
•		•			13, 14, 15, 16, 17, 18, 19, 20,		
					21, 22, 23, 24, 25, 26, 27, 28, 29		